

Preparing to MIG weld in the workshop

Ensure that workshop tools and equipment are protected from flying sparks or heat

Clear the welding area of any flammable materials such as paper, rags or flammable liquids

Remove tools and equipment not needed and use a welding curtain

Regularly leak test the welding gas system to ensure there are no leaks at the regulators, hoses, fittings, and hand piece

Keep the cylinders away from any sources of heat

Always leave the gas cylinders turned off when not in use

Always know where all the fire extinguishers are located and be aware of the type and purpose