Safety Precautions when MIG welding to ensure environmental safety
Keep area clean, free from grease oil and paints
Clear all flammables from the area
Ensure fire extinguishers are accessible and in working order
Keep flames, sparks away from cylinders and hoses
Do not weld on containers that have flammable materials